

Complementary manual for W040 Water Level Sensor, now with sensor cable (102 cm)

1. Before you begin - the sensor Cable should be connected to the WL module at least 10 seconds



2. Follow the instructions in the app and press OK at "Connection ready"



3. At the instruction "Keep position until ready" Disconnect the sensor cable from the WL module.



4. When connection OK/Success is displayed, reconnect the sensor cable to the WL module and the connection is completed.



5. The sensor part of the sensor cable is placed in the space where water is to be detected. When both metal pins fall underwater, the sensor will send SMS alarms.



If the sensor cable comes loose from the WL module, an SMS with water alarm will be sent.

Note! The WL module must be placed where the module is not exposed to water.